


# Net Build



- Manufacturing process used to locate outer panels
- Stamps reference point on parts
- Formed, pierced, or lanced

◀ C-1 C-2 C-3 C-4 ▶

Topic A B **C** D E



◀ Module Menu ▶ Quit

# Coined Surfaces



- Usually not provided in replacement parts
- May require extra steps during repair process



# Hydroforming



- Creates parts with no flanges
- Requires alternate anchoring locations
- Corrosion less of a concern
- Parts may be sectioned

◀ C-1 C-2 C-3 C-4 ▶

Topic A B C D E



◀ Module Menu ▶ Quit

# Adhesively Bonded Panels



- Weld-bonding
- Bonding with fasteners

